

## **Telstra BigPond Broadband ADSL service.**

The following ADSL equipment has been certified by manufacturers as having successfully passed interoperability tests. Please confirm whether this equipment is supported by your ISP.

The equipment manufacturer/vendor has independently certified their equipment to meet the requirements of IP 1149. Telstra does not guarantee the performance or supply of this equipment. Note the specific model numbers of the certified ADSL equipment, the model approval *does not* imply all that vendor's equipment complies with IP 1149.

### **List of certified ADSL Equipment**

#### **Modems/Routers (Equipment Certification date in brackets)**

Askey/Dynalink - ALE 070 (08.01.2001)  
Askey/Dynalink - ALH 110 (21.03.2001)  
Askey - RTA100 ADSL Modem (25.10.2002)  
Billion Electric - BIPAC-711 CE ADSL Modem (25.10.2002)  
Billion/PC Range - BIPAC-5100 Router 4-port (28.04.2004)  
Billion/PC Range - BIPAC-7402 Router/Firewall 4-port (28.05.2004)  
Billion/PC Range - BIPAC 5100W Wireless router (12.05.2004)  
Cisco WAG54G, Wireless Router ADSL Modem, 4 port (04.03.2004)  
Cisco WIC -1ADSL-DG (30.06.2003)  
Cisco 827 (19.02.2001)  
Cisco 827H (11.07.2002)  
Cisco 827-4V (19.02.2001)  
Cisco 837 (01.04.2003)  
Cisco Linksys AG041 - modem/router, 4-port Switch (19.04.2004)  
Cisco SOHO77 (29.11.2001)  
Cisco SOHO77H (11.07.2002)  
Cisco SOHO97 (01.04.2003)  
D-Link ADSL Modem - DSL 100D (08.08.2001)  
D-Link ADSL Modem - DSL 300 (08.08.2001)  
D-Link ADSL Modem - DSL 302G (29.08.2003)  
D-Link ADSL Modem - DSL 500 (08.08.2001)  
D-Link ADSL Modem - DSL 504 (08.08.2001)  
D-Link ADSL Modem - DSL 200 USB (30.04.2004)  
D-Link ADSL Modem - DSL 300g Ethernet(30.04.2004)  
D-Link ADSL Modem - DSL 504g Router(30.04.2004)  
Efficient Networks (C10 Communications) - Speedstream 3060 (08.01.2001)  
Efficient Networks (C10 Communications) - Speedstream 4060 (08.01.2001)  
Efficient Networks (C10 Communications) - Speedstream 5260 (08.01.2001)  
Efficient Networks (Siemens) - Speedstream 5400 (07.04.2003)  
Efficient Networks (C10 Communications) - Speedstream 5660 (21.03.2001)  
Efficient Networks (C10 Communications) - Speedstream 5667 (10.09.2001)  
Efficient Networks (C10 Communications) - Speedstream 5861 (21.03.2001)  
Efficient Networks (Siemens) - Speedstream 6300 Wireless/Gateway (14.05.2004)  
Juni NetAce - ADSL USB Modem (15.01.2003)  
Juni NetElite 2000ES - ADSL 4 port Modem (15.01.2003)  
Juni/Samsung SAM-215 USB Modem (18.07.2001)  
Juni/Samsung SAM-335A Ethernet Modem (18.07.2001)  
NetComm ADSL Modem - BusinessSmart (08.08.2001)  
Netcomm ADSL Modem, Firewall - NB5580 (06.02.2004)  
Netcomm ADSL Modem, Firewall/Wireless - NB5580W (06.02.2004)

Netcomm ADSL Modem, NB3 Ethernet/USB (15.03.2004)  
NetComm ADSL Modem - USB (NB1200) (27.08.2002)  
NetComm ADSL USB/Ethernet Router Modem - NB5 (29.06.2004)  
NetComm ADSL Modem - NB2, USB (12.05.2004)  
NetComm ADSL Router Modem - NB1300 (20.11.2002)  
NetComm ADSL Router/Modem - NB1300+4 (12.05.2004)  
Netgear ADSL Router/Modem - DG632 (05.08.2004)  
Open 501r ADSL Router Modem (05.04.2002)  
Siemens - Speedstream 4200, ADSL USB/Ethernet Router Modem (27.07.2004)  
SMC/Barricade - SMC 7804WBRA, wireless/Router 4-port (28.04.2004)  
Thomson SpeedTouch - 510 ADSL Modem (15.01.2003)  
Thomson SpeedTouch - 530 ADSL Modem (15.01.2003)  
Thomson SpeedTouch - 570 Wireless ADSL Modem (22.10.2003)  
Thomson/Alcatel SpeedTouch Home (04.08.2000)  
Thomson/Alcatel SpeedTouch Pro (04.08.2000)  
Thomson/Alcatel SpeedTouch Pro (4 port) (10.09.2001)  
Thomson/Alcatel SpeedTouch Pro (Firewall) (09.10.2001)  
Thomson/Alcatel SpeedTouch PCNIC (04.08.2000)  
Thomson/Alcatel SpeedTouch USB (04.08.2000)  
UHS - Ultralink Business Gateway 203021 ADSL Modem (09.12.2003)

## **Filters/Splitters**

### **(Certified to RCIT.0004):**

ADC/Covertel - Distributed Splitter, RJ11/45 - 3 port, IPC-EXAUS-01  
C10 Communications - Distributed Splitter, 600 series, C10645E  
C10 Communications - Distributed Splitter, RJ11/45 series, C10245E  
C10 Communications - Distributed Splitter, Wall Mount, C10345E  
C10 Communications - Remote Splitter, C10100E

### **(NOT Certified to RCIT.0004):**

- \* Advanced Telephone Systems 2000 Pty Ltd
- \* Alcatel - In-Line, Part No. 3AU 04805 ABAA
- \* Askey/Dynalink - In-Line, DT60-002BA
- \* C10 Communications (Dynamic) - In-Line, C10290
- \* C10 Communications - In-Line, C10611 & C10611T
- \* C10 Communications - In-Line, C10645 & C10645T
- \* C10 Communications - In-Line, C10610
- \* C10 Communications - In-Line, C10211
- \* C10 Communications - In-Line, C10111
- \* C10 Communications - In-Line, C10145
- \* C10 Communications - In-Line, C10245
- \* D-Link - Central, DSL-10SP
- \* D-Link - Central, DSL-10CF
- \* D-Link - In-Line, DSL-10MF
- \* Telephone Equipment - Central, TE-ACP20AUS01

**\* NOTE: These filters/splitters do not conform to the current Splitter Specification RCIT.0004 and certification has now been withdrawn for all new installations. See below for the latest copy of this specification. These existing \*splitters will not need to be recalled or replaced, the grand father rule will apply. These \*splitters will only need to be replaced with the RCIT.0004 certified splitters if there are CPE issues.**

## **Client Software**

iVasion, WinPoET version 2.0  
Network TeleSystems (NTS), EnterNet 300 version 1.34

Note: This list will be continually updated as more ADSL equipment is approved. See below for details of the approvals process and the third-party test houses that can perform interoperability tests.